

Oil Field Environmental Incident Summary

Incident: 20140320104026 **Date/Time of Notice:** 03/20/2014 10:40
Responsible Party: ZAVANNA, LLC
Well Operator: ZAVANNA, LLC
Well Name: PVT. FRAZIER 1-34H
Field Name: BRIAR CREEK **Well File #:** 16569
Date Incident: 3/14/2014 **Time Incident:** 15:30 **Facility ID Number:**
County: MCKENZIE **Twp:** 152 **Rng:** 104 **Sec:** 34 **Qtr:**
Location Description: Wellsite and Flood plane

Submitted By: Andrew Tooley **Received By:**

Contact Person: Michael Weber
1200 17TH STREET STE 1100
1200 17th Street Suite 1100
DENVER, CO 80202

General Land Use: Other - Described Above **Affected Medium:** Soil and Water

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.8 Mile

Type of Incident Other

Release Contained in Dike No

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Barrels			55	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 4/29/2014 **Clean Up Concluded:**

Risk Evaluation:

None

Areal Extent:

.5 miles down the flood plane to the NW of the wellsite location.

Potential Environmental Impacts:

Surface Water, Topsoil

Action Taken or Planned:

Well was shut in as soon as possible to prevent additional oil from spilling into wellsite and down flood plane. State officials were notified and 3 different cleanup crews were notified to start the cleanup process.

Wastes Disposal Location: Dishon Disposal, INC.

Agencies Involved:**Updates**

Date: 3/20/2014 **Status:** Reviewed; Followup Required **Staff:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted the surface waters of the state. Followup is necessary.

Date: 3/21/2014 **Status:** Inspected; More Followup Required **Staff:** Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted area known as 4 Mile Creek in Big Oxbow Wildlife Management Area. EPA, NDDoH, NDGF, FWS have all been involved with inspections. Remediation is ongoing at this time. Location access is limited to boat traffic only. Garner Environmental is the main cleanup contractor responding. Zavanna/Garner IAP has been received this date and will be reviewed before additional inspections.